

	A	B	C
1	Garage Door Audit Mar 20 2025		
2			
3	<b>Unit</b>	<b>Year</b>	<b>Notes</b>
4	<b>1198</b>	<b>2002</b>	Door Replaced
5		<b>2008</b>	Door Replaced
6		<b>2009</b>	Operator Replaced
7	<b>1200</b>	<b>2007</b>	Door Replaced
8		<b>2016</b>	Roller Replaced
9	<b>1202</b>	<b>2000</b>	Overhead door 950 screw drive 1/2
10		<b>2011</b>	Door Replaced
11	<b>1203</b>	<b>1993</b>	Operator Replaced
12		<b>2002</b>	Operator Replaced
13		<b>2016</b>	Door Replaced
14			Operator Replaced
15	<b>1204</b>	<b>1995</b>	Opener Replaced
16		<b>2000</b>	Door Repair 10' Cable & Rollers
17			Door Replaced
18		<b>2001</b>	Spring Replaced
19	<b>1205</b>	<b>2023</b>	Seals Replaced
20		(blank)	Replacement Not Reported
21	<b>1206</b>	<b>2000</b>	Door Module Replaced
22		<b>2016</b>	Door Replaced
23			Operator Replaced
24	<b>1207</b>	<b>2007</b>	Door Replaced
25		<b>2011</b>	Spring Replaced
26		<b>2018</b>	Door Replaced
27	<b>1208</b>	<b>1996</b>	Opener Replaced
28		<b>2010</b>	Door Replaced
29	<b>1209</b>	<b>1994</b>	Opener Replaced
30		<b>2014</b>	Door Replaced
31			Operator Replaced
32	<b>1210</b>	(blank)	Door Replaced
33	<b>1212</b>	<b>2000</b>	Door Adjustment
34		<b>2011</b>	Door Replaced
35	<b>1214</b>	<b>2012</b>	Door Replaced
36		<b>2024</b>	Front Replaced Cedar Siding with H
37	<b>1216</b>	<b>2011</b>	Operator Replaced
38		(blank)	Replacement Not Reported
39	<b>1218</b>	<b>2013</b>	Spring Replaced
40		<b>2015</b>	Door Replaced
41			Operator Replaced
42	<b>1220</b>	<b>2002</b>	Door Replaced
43		<b>2010</b>	Spring Replaced
44		<b>2015</b>	Spring Replaced
45	<b>1221</b>	<b>2024</b>	operator replaced/sensors installed
46		(blank)	Replacement Not Reported
47	<b>1222</b>	<b>2016</b>	Door Replaced
48			Operator Replaced
49		<b>2024</b>	Operator Replaced - Wiring

	A	B	C
50	<b>1223</b>	<b>2017</b>	Door Replaced
51		(blank)	Door Latch Replaced
52	<b>1224</b>	<b>2000</b>	Door Adjustment
53		<b>2017</b>	Door Replaced
54			Operator Replaced
55	<b>1225</b>	<b>2009</b>	Door Replaced
56		<b>2024</b>	Door Replaced at Owners Expense
57	<b>1226</b>	<b>2017</b>	Door Replaced
58	<b>1227</b>	<b>2012</b>	Door Replaced
59		<b>2024</b>	operator replaced/sensors installed
60	<b>1228</b>	<b>2013</b>	Door Replaced
61			Operator Replaced
62	<b>1229</b>	<b>2011</b>	Spring Replaced
63		<b>2014</b>	Door Replaced
64			Operator Replaced
65	<b>1230</b>	(blank)	Replacement Not Reported
66	<b>1231</b>	<b>2009</b>	Door Replaced
67	<b>1232</b>	<b>2015</b>	Door Replaced
68			Spring Replaced
69	<b>1233</b>	<b>2000</b>	Door Repair
70		(blank)	Door Replaced
71	<b>1234</b>	<b>2023</b>	Spring Replaced
72		(blank)	Replacement Not Reported
73	<b>1236</b>	<b>2012</b>	Cable Replaced
74			Spring Replaced
75		(blank)	Replacement Not Reported
76	<b>1237</b>	<b>1999</b>	Replace add tesion, lube, change ro
77		<b>2012</b>	Operator Replaced
78		<b>2016</b>	Door Replaced
79	<b>1238</b>	<b>2009</b>	Spring Replaced
80		(blank)	Replacement Not Reported
81	<b>1239</b>	<b>2010</b>	Door Replaced
82		<b>2016</b>	Operator Replaced
83		<b>2023</b>	Door Springs & Bearings Replaced
84	<b>1240</b>	<b>1996</b>	Opener Repair
85		<b>2014</b>	Door Replaced
86			Operator Replaced
87	<b>1241</b>	<b>2011</b>	Door Replaced
88	<b>1242</b>	<b>2002</b>	Door Replaced
89		<b>2020</b>	Door Replaced
90	<b>1243</b>	<b>2000</b>	Door Replaced
91		<b>2001</b>	Door Repair
92		<b>2012</b>	Door Replaced
93			Operator Replaced
94	<b>1244</b>	(blank)	Replacement Not Reported
95	<b>1246</b>	<b>2013</b>	Spring Replaced
96		<b>2015</b>	Door Replaced
97			Operator Replaced
98		(blank)	Switch Repair

	A	B	C
99	<b>1248</b>	<b>2011</b>	Spring Replaced
100		<b>2013</b>	Door Replaced
101			Operator Replaced
102	<b>1250</b>	(blank)	Door Replaced
103			Notes Track Replaced, owner paid
104	<b>1252</b>	<b>2017</b>	Door Replaced
105			Operator Replaced
106			Spring Replaced
107	<b>1254</b>	<b>2016</b>	Door Replaced
108			Operator Replaced
109			Spring Replaced
110	<b>1256</b>	<b>2017</b>	Door Replaced
111	<b>1258</b>	<b>2002</b>	Door Replaced
112	<b>1260</b>	<b>2017</b>	Door Replaced
113			Operator Replaced
114			Spring Replaced
115	<b>1261</b>	<b>2012</b>	Door Replaced
116		<b>2017</b>	Operator Replaced
117		<b>2022</b>	Spring Replaced
118	<b>1262</b>	<b>2005</b>	Operator Replaced
119		<b>2012</b>	Door Replaced
120	<b>1264</b>	(blank)	Door Replaced
121	<b>1265</b>	<b>2018</b>	Door Replaced
122			Spring Replaced
123	<b>1266</b>	<b>2011</b>	Door Replaced
124		<b>2017</b>	Operator Replaced
125	<b>1268</b>	<b>2000</b>	Door Replaced
126	<b>5069</b>	(blank)	Replacement Not Reported
127	<b>5071</b>	<b>2000</b>	Door Repair
128		<b>2015</b>	Door Replaced
129			Operator Replaced
130	<b>5073</b>	<b>2013</b>	Door Replaced
131			Operator Replaced
132		<b>2024</b>	spring and bearings replaced
133	<b>5075</b>	<b>2001</b>	Door Repair
134		<b>2009</b>	Door Replaced
135	<b>5077</b>	<b>2001</b>	Door Repair
136		<b>2011</b>	Door Replaced
137		<b>2013</b>	Operator Replaced
138	<b>5079</b>	<b>2002</b>	Door Replaced
139		<b>2017</b>	Door Replaced
140			Operator Replaced
141	<b>5081</b>	<b>1999</b>	Door Replaced
142		<b>2012</b>	Door Replaced
143			Operator Replaced
144		<b>2023</b>	Door Spring Replaced